

# Home Report

269 Perth Road  
Dundee DD2 1JP

Date of Valuation: 03/12/2024

**UK Chartered Surveyors  
and Property Consultants**

[g-s.co.uk](http://g-s.co.uk)

# single survey

survey report on:

|                  |                                     |
|------------------|-------------------------------------|
| Property address | 269 Perth Road<br>Dundee<br>DD2 1JP |
| Customer         | Catherine Muir                      |
| Prepared by      | Graham + Sibbald LLP                |

# 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

|             |   |
|-------------|---|
| Description | The subjects comprise a substantial semi-detached two storey villa which we understand is B listed. |
|-------------|---|

|               |  |
|---------------|--|
| Accommodation | GROUND FLOOR - Vestibule, Hallway, Lounge, Dining Room, Study, Breakfasting Kitchen, Large Utility Room, Cloakroom with WC and Side Porch.<br><br>FIRST FLOOR - 5 Bedrooms, Main Shower Room with WC and Bathroom with WC. |
|---------------|--|

|  |               |
|--|---------------|
|  | 275 sq metres |
|--|---------------|

|                            |   |
|----------------------------|---|
| Neighbourhood and location | The property is located approximately one mile west of Dundee City Centre within a good class established residential district at the junction of Perth Road and Hyndford Street. Surrounding properties are mainly of a mixed residential nature and the property enjoys panoramic views towards the Tay Estuary. Adequate secondary shopping, public transport, social and educational facilities can be found within easy reach. |
|----------------------------|---|

|                  |                     |
|------------------|---------------------|
| Age (year built) | Erected around 1862 |
|------------------|---------------------|

|         |               |
|---------|---------------|
| Weather | Sunny and dry |
|---------|---------------|

|                |  |
|----------------|--|
| Chimney stacks | <p>Visually inspected with the aid of binoculars where appropriate.</p> <p>The chimney stacks are of ornate stonework served with metal and cement flashings, where viewed. A limited inspection was possible from ground level.</p> |
|----------------|--|

|                              |   |
|------------------------------|---|
| Roofing including roof space | <p>Sloping roofs were visually inspected with the aid of binoculars where appropriate.</p> <p>Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.</p> <p>Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.</p> <p>The roof is of pitched timber construction externally clad in slate with zinc ridging, hips and valleys. There are flat coverings over the vestibule and bay projection and there is also a flat platform area around the rooflight which could not be viewed. Access to the roof space is via a hatch within the shower room area. This hatch gives access to a lowered ceiling area with the main hatch at a higher level. Due to the location of the hatch, a very restricted inspection of the roof timbers was possible. It was noted that the roof space has been insulated and insulation is laid over joists. This severely restricted our inspection.</p> |
|------------------------------|---|

|                    |   |
|--------------------|---|
| Rainwater fittings | <p>Visually inspected with the aid of binoculars where appropriate.</p> <p>The rainwater goods are of cast iron and PVC design.</p> |
|--------------------|---|

|                                     |  |
|-------------------------------------|--|
| Main walls                          | <p>Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected.</p> <p>The main walls are of solid stone construction with rendered and painted window margins at points. An ornate balustrade is provided over the side vestibule.</p>   |
| Windows, external doors and joinery | <p>Internal and external doors were opened and closed where keys were available.</p> <p>Random windows were opened and closed where possible.</p> <p>Doors and windows were not forced open.</p> <p>The windows are of double glazed timber sash, single glazed timber sash and single glazed timber sash with secondary glazing. Windows are stained glass at ground floor level within the hallway and vestibule areas.</p> <p>Access to the property is via the original timber panelled entry doors.</p> |
| External decorations                | Visually inspected.  |
| Conservatories / porches            | Not applicable.  |
| Communal areas                      | Not applicable.  |
| Garages and permanent outbuildings  | <p>Visually inspected.</p> <p>There is a single garage with workshop area which is semi-detached and lies to the rear of the property, accessed from Shaftesbury Road. This is of stone and brick construction with a slate roof while the workshop area appears timber framed and timber clad with a flat felt roof over.</p>   |

|                              |   |
|------------------------------|---|
| Outside areas and boundaries | <p>Visually inspected.</p> <p>The subjects are served with a corner site enclosed with hedging and stone retaining walls. Off-street parking is provided to the rear and there is a cobbled courtyard area to the side and rear.</p>  |
| Ceilings                     | <p>Visually inspected from floor level.</p> <p>The ceilings are of timber lath and plaster throughout with a papered or painted finish. Ornate features are provided within the main apartments. Lowered plasterboard ceilings have been formed at points within.</p>   |
| Internal walls               | <p>Visually inspected from floor level.</p> <p>Using a moisture meter, walls were randomly tested for dampness where considered appropriate.</p> <p>The internal walls are of brick construction plastered on the hard, timber lath and plaster and timber stud overlaid in plasterboard. Internal surfaces are papered and painted and there are areas of tiling within the kitchen, utility room and sanitary areas.</p>  |
| Floors including sub floors  | <p>Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.</p> <p>Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so , and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.</p> <p>The flooring within is of suspended timber construction and also solid concrete and suspended concrete which is tiled. Due to fitted carpets and floor coverings no detailed inspection was possible of the floor timbers and accordingly we cannot comment on their soundness or otherwise. No sub-floor inspection was possible as no hatch could be located.</p> |

|                                       |   |
|---------------------------------------|---|
| Internal joinery and kitchen fittings | <p>Built-in cupboards were looked into but no stored items were moved.</p> <p>Kitchen units were visually inspected excluding appliances.</p> <p>The internal doors are of original timber panelled and timber and glazed design.</p> <p>The kitchen units are serviceable and older units are provided within the utility room.</p> <p>A stone stair adjoins ground to upper floor level.</p>                  |
| Chimney breasts and fireplaces        | <p>Visually inspected. No testing of the flues or fittings was carried out.</p> <p>Marble fireplaces are provided within the lounge, main bedroom and mid bedroom and these are served with living flame gas fires. Any other fireplaces have been removed/blocked and we presume adequately vented.</p>  |
| Internal decorations                  | <p>Visually inspected.</p>  |
| Cellars                               | <p>Visually inspected where there was safe and purpose-built access.</p> <p>There is a small wine cellar area accessed from the kitchen.</p>  |
| Electricity                           | <p>Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.</p> <p>Mains supply.</p> |

|     |   |
|-----|---|
| Gas | <p>Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.</p> <p>Mains supply.</p> |
|-----|---|

|                                    |   |
|------------------------------------|---|
| Water, plumbing, bathroom fittings | <p>Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.</p> <p>It should be appreciated that concealed areas beneath and around baths and shower trays could not be inspected. Water spillage in these areas can result in dampness/decay and no comment can be made on inaccessible areas. Waterproof seals in sanitary areas should be checked and maintained on a regular basis.</p> <p>Mains supply of water. There is a sink unit within the kitchen and Belfast sinks are provided within the utility room. Fittings within the cloakroom and bathroom areas are on traditional lines and modern fittings are provided within the shower room area. No view was possible of any cold water tank.</p> |
|------------------------------------|---|

|                       |  |
|-----------------------|--|
| Heating and hot water | <p>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.</p> <p>Space heating is by means of a full gas fired system and the radiators are served with mixed piping and partial individual thermostats. There is a Viessmann regular boiler within the side porch and this is served with a fan assisted flue. The central heating system provides domestic hot water along with an electrical immersion heater. There is a large insulated hot water cylinder within the utility room area.</p> |
|-----------------------|--|



|          |   |
|----------|---|
| Drainage | <p>Drainage covers etc were not lifted.</p> <p>Neither drains nor drainage systems were tested.</p> <p>Presumed to be connected to the main public sewer.</p> |
|----------|---|

|                                |  |
|--------------------------------|--|
| Fire, smoke and burglar alarms | <p>Visually inspected.</p> <p>No tests whatsoever were carried out to the system or appliances.</p> <p>New smoke alarm standards were introduced in Scotland in February 2022 and it is likely that some properties may require additional works to meet these standards. In instances where alarms are in place, no tests whatsoever have been carried out and we cannot confirm if the system complies with the most recent regulations. Any potential purchaser should satisfy themselves as to whether the current system meets with regulations or otherwise.</p> <p>Smoke and burglar alarms are provided within the property.</p> |
|--------------------------------|--|

|                                 |  |
|---------------------------------|--|
| Additional limits to inspection | <p>Insulation has been laid over the roof joists and accordingly a head and shoulders inspection of the roof space was possible only.</p> <p>It is outwith the scope of this inspection to determine whether or not asbestos based products are present within the property. Asbestos was widely used in the building industry until around 1999, when it became a banned substance. If you have any concerns you should engage the services of a qualified asbestos surveyor.</p> <p>No inspection for Japanese Knotweed was carried out and unless otherwise stated for the purpose of this report, it is assumed that there is no Japanese Knotweed within the boundaries of the property or neighbouring properties.</p> <p>It should be appreciated that the Home Report inspection is a non-disruptive visual inspection of the property as at the date of inspection and that we are unable to inspect parts of the property which are concealed or covered by floor coverings or contents in place at that time. Once vacant, defects may be apparent that could not be detected during our survey. Changing weather conditions can also affect aspects of the property which would not be apparent at the time of inspection.</p> |
|---------------------------------|--|

## Sectional Diagram showing elements of a typical house





|    |                          |
|----|--------------------------|
| 1  | Chimney pots             |
| 2  | Coping stone             |
| 3  | Chimney head             |
| 4  | Flashing                 |
| 5  | Ridge ventilation        |
| 6  | Ridge board              |
| 7  | Slates/tiles             |
| 8  | Valley guttering         |
| 9  | Dormer projection        |
| 10 | Dormer flashing          |
| 11 | Dormer cheeks            |
| 12 | Sarking                  |
| 13 | Roof felt                |
| 14 | Trusses                  |
| 15 | Collar                   |
| 16 | Insulation               |
| 17 | Parapet gutter           |
| 18 | Eaves guttering          |
| 19 | Rainwater downpipe       |
| 20 | Verge boards / skewes    |
| 21 | Soffit boards            |
| 22 | Partition wall           |
| 23 | Lath / plaster           |
| 24 | Chimney breast           |
| 25 | Window pointing          |
| 26 | Window sills             |
| 27 | Rendering                |
| 28 | Brickwork / pointing     |
| 29 | Bay window projection    |
| 30 | Lintels                  |
| 31 | Cavity walls / wall ties |
| 32 | Subfloor ventilator      |
| 33 | Damp proof course        |
| 34 | Base course              |
| 35 | Foundations              |
| 36 | Solum                    |
| 37 | Floor joists             |
| 38 | Floorboards              |
| 39 | Water tank               |
| 40 | Hot water tank           |





Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.



## 2. Condition





This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

| Category 3   | Category 2  | Category 1                               |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |





|   |   |  |
|---|---|--|
|    | <b>Structural movement</b>  |  |
| Repair  | 1   |  |
| Notes   | Movement has affected the property observed in the form of cracking to lintels and sills externally while internally there is a slight run in the flooring timbers and some plaster cracking has occurred. Historic repairs have been carried out at points. On the basis of a single inspection this appears to be longstanding and non-progressive.   |  |
|  | <b>Dampness, rot and infestation</b>  |  |
| Repair category   | 2   |  |
| Notes   | <p>A check should be made to ascertain if any timber specialist repair works have been carried out within the property in the past and all reports and guarantees should be obtained, studied and authenticated prior to purchase.</p> <p>Staining was noted within the roof space and higher than average damp readings were obtained within the utility room area, and also within the wine cellar area although it is noted that some damp proof membrane repairs have been carried out within this area. As a precautionary measure it is recommended that a timber specialist firm is instructed prior to purchase to carry out a full inspection of the property.</p> |  |

|   |   |  |
|---|---|--|
|    | Chimney stacks  |  |
| Repair category   | 2   |  |
| Notes   | Typical weathering has occurred and flashings do require regular maintenance. Some weathered stonework and pointing was noted.  |  |
|    | Roofing including roof space  |  |
| Repair category   | 2   |  |
| Notes   | <p>This is the original roof covering which is typically weathered although it is understood that annual maintenance is carried out. No evidence of significant defect is apparent although there are some cracked slates. As stated, staining has occurred within the roof space.</p> <p>The roof covering is now of an age where ongoing and regular maintenance will be required and it would be prudent to seek the advice of a roofing contractor to comment on its current condition and expected lifespan.</p> |  |
|  | Rainwater fittings  |  |
| Repair category   | 1   |  |
| Notes   | At the time of our inspection there was no evidence of damp staining/water staining on wall surfaces which would indicate leakage. It should be noted that it was not raining at the time of our inspection.  |  |
|  | Main walls  |  |
| Repair category   | 2   |  |
| Notes   | Stonework is weathered and scaling at points and the painted render finish is rather weathered and is affected by some deterioration. As stated previously, there are some cracked sills and lintels, and some historic repairs have been carried out.  |  |


|   |   |  |
|---|---|--|
|    | Windows, external doors and joinery   |  |
| Repair category   | 2   |  |
| Notes   | <p>Many of the windows are original and affected by typical ageing. One or two cracked panes were noted and externally the timber frames and sills are typically weathered.</p> <p>Windows can be problematic and over time the operation of the windows can be affected and opening mechanisms damaged. It is therefore likely that maintenance/repair will be required as part of an ongoing maintenance programme.</p> |  |
|    | External decorations  |  |
| Repair category   | 2   |  |
| Notes   | This would benefit from being freshened once the windows have been overhauled.  |  |
|  | Conservatories / porches  |  |
| Repair category   | N/A   |  |
| Notes   | Not applicable.   |  |
|  | Communal areas  |  |
| Repair category   | N/A   |  |
| Notes   | Not applicable.   |  |
|  | Garages and permanent outbuildings  |  |

|   |   |
|---|---|
| Repair category   | 2   |
| Notes   | No evidence of significant defect is apparent and it is noted that historic repairs have been carried out. Typical weathering has occurred to the stonework and the roof covering is original and weathered. Staining and condensation was noted internally to panelled ceilings. |
|    | <b>Outside areas and boundaries</b>   |
| Repair category   | 2   |
| Notes   | It is evident that some repointing repairs are being carried out to the retaining walls in the past although these are rather undulating at points and bulging towards the front corner of the site. Retaining walls do require regular maintenance.                              |
|   | <b>Ceilings</b>   |
| Repair category   | 1   |
| Notes   | Minor plaster cracking has occurred. Timber lath and plaster surfaces do have a limited life.   |
|  | <b>Internal walls</b>   |
| Repair category   | 1   |
| Notes   | The internal walls are largely covered with decorative finishes. During routine redecoration some plaster filling may be necessary.<br><br>Some plaster cracking has occurred within the front first floor bedroom area.  |
|  | <b>Floors including sub-floors</b>  |
| Repair category   | 1   |

|   |   |
|---|---|
| Notes   | Areas of loose/uneven flooring were noted.<br><br>There is a slight run in the flooring timbers due to past internal movement.  |
|    | <b>Internal joinery and kitchen fittings</b>  |
| Repair category   | 1   |
| Notes   | The internal joinery is generally in keeping with the age and type of property and appeared in good condition consistent with age.<br><br>The kitchen units are on semi-modern lines and affected by typical wear and tear. |
|    | <b>Chimney breasts and fireplaces</b>   |
| Repair category   | 1   |
| Notes   | All flue linings should be checked, repaired if necessary and swept prior to the fires being reused.<br><br>The gas fires were not checked or tested.   |
|  | <b>Internal decorations</b>   |
| Repair category   | 1   |
| Notes   | The property is generally in fresh decoration throughout.   |
|  | <b>Cellars</b>  |
| Repair category   | N/A   |
| Notes   | Not applicable.   |

|   |   |  |
|---|---|--|
|    | <h2 style="text-align: center;">Electricity</h2>  |  |
| Repair category   | 2   |  |
| Notes   | <p>The electrical system is on mixed lines and as such we recommend that it be checked and upgraded as necessary by an NICEIC/SELECT registered Electrical Contractor.</p>  |  |
|    | <h2 style="text-align: center;">Gas</h2>  |  |
| Repair category   | 1   |  |
| Notes   | <p>In the interest of safety all gas appliances should be checked by a Gas Safe Registered Engineer.</p>  |  |
|  | <h2 style="text-align: center;">Water, plumbing and bathroom fittings</h2>  |  |
| Repair category   | 1   |  |
| Notes   | <p>The plumbing and fittings appear of copper/PVC piping where seen and appeared in serviceable condition but was not tested.</p> <p>The sanitary fittings are of a serviceable and modern style and type.</p> <p>It should be appreciated that concealed areas beneath and around baths and shower trays could not be inspected. Water spillage in these areas can result in dampness/decay and no comment can be made on inaccessible areas.</p> <p>Waterproof seals in sanitary areas should be checked and maintained on a regular basis.</p> |  |
|  | <h2 style="text-align: center;">Heating and hot water</h2>  |  |
| Repair category   | 1   |  |
| Notes   | <p>Some radiators and pipework are on older lines although it is noted that the boiler is modern. The system was not checked or tested. Ongoing maintenance and servicing should be carried out.</p>  |  |



|   |   |  |
|---|---|--|
|  | <h2 style="margin: 0;">Drainage</h2>  |  |
| <p>Repair category</p>  | <p>1</p>  |  |
| <p>Notes</p>  | <p>The property is thought to be connected to a main sewer. There was no surface evidence to suggest the system is choked or leaking.</p> |  |

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

|                                       |     |
|---------------------------------------|-----|
| Structural movement                   | 1   |
| Dampness, rot and infestation         | 2   |
| Chimney stacks                        | 2   |
| Roofing including roof space          | 2   |
| Rainwater fittings                    | 1   |
| Main walls                            | 2   |
| Windows, external doors and joinery   | 2   |
| External decorations                  | 2   |
| Conservatories / porches              | N/A |
| Communal areas                        | N/A |
| Garages and permanent outbuildings    | 2   |
| Outside areas and boundaries          | 2   |
| Ceilings                              | 1   |
| Internal walls                        | 1   |
| Floors including sub-floors           | 1   |
| Internal joinery and kitchen fittings | 1   |
| Chimney breasts and fireplaces        | 1   |
| Internal decorations                  | 1   |
| Cellars                               | N/A |
| Electricity                           | 2   |
| Gas                                   | 1   |
| Water, plumbing and bathroom fittings | 1   |
| Heating and hot water                 | 1   |
| Drainage                              | 1   |

|  |
|--|
| <b>Category 3</b>  |
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. |
| <b>Category 2</b>  |
| Repairs or replacement requiring future attention, but estimates are still advised.  |
| <b>Category 1</b>  |
| No immediate action or repair is needed.   |

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

### 3. Accessibility information

#### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property: In flatted developments the main entrance would be the flat's own entrance door, not the external door to the communal stair. The three steps or fewer are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, Unrestricted parking includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

| 1. Which floor (s) is the living accommodation on?                                     | Ground & First |   |    |   |
|--|----------------|---|----|---|
| 2. Are there three steps or fewer to a main entrance to a property?                    | Yes            | X | No |   |
| 3. Is there a lift to the main entrance door of the property?                          | Yes            |   | No | X |
| 4. Are all door openings greater than 750mm?   | Yes            |   | No | X |
| 5. Is there a toilet on the same level as the living room and kitchen?                 | Yes            | X | No |   |
| 6. Is there a toilet on the same level as a bedroom?                                   | Yes            | X | No |   |
| 7. Are all rooms on the same level with no internal steps or stairs?                   | Yes            |   | No | X |
| 8. Is there unrestricted parking within 25 metres of an entrance door to the building? | Yes            | X | No |   |

#### 4. Valuation and conveyance issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated cost for insurance purposes.

##### Matters for a solicitor or licensed conveyancer

We are unaware of any adverse planning proposals affecting the subjects although this should be confirmed by obtaining a Property Enquiry Certificate.

Absolute Ownership assumed. We are unaware of any easements, servitudes or rights of way which may adversely affect the property. This point should be confirmed by reference to the Title Deeds.

It is recommended that where repairs, defects or maintenance items have been identified interested parties make appropriate enquiries in order to satisfy themselves of potential costs and the extent of the works required prior to submitting a legal offer to purchase.

The property, we understand, is B listed. Alterations have been carried out historically and it is assumed that any necessary consents were obtained. This will require to be confirmed.


It appears that timber specialist repair works have been carried out within the property in the past and all reports and guarantees should be obtained, studied and authenticated prior to purchase.

##### Estimated reinstatement cost for insurance purposes

It is assumed that insurance cover is obtainable on normal terms. The guidance figure is the estimate of costs for reinstating the subjects as at the date of inspection based on information provided by the Building Cost Information Service (BCIS). It is recommended that this figure is kept under regular review to ensure that you have adequate insurance cover. We are of the opinion that the subjects should be insured for buildings reinstatement purposes for a sum of not less than (One Million, Two Hundred and Fifty Thousand Pounds Sterling).

##### Valuation and market comments

We are of the opinion that the market value of the subjects all as previously described and on a vacant possession basis would be fairly stated in the region of (Five Hundred and Twenty Five Thousand Pounds Sterling).

|                |   |
|----------------|---|
| Report author  | Graham Tonner MRICS   |
| Address        | Seabraes House, 18 Greenmarket, Dundee. DD1 4QB.  |
| Signed         | <br>Graham Tonner MRICS<br>For and on behalf of Graham + Sibbald LLP |
| Date of report | 3/12/2024   |

## TERMS AND CONDITIONS OF SINGLE SURVEY

### GENERAL

#### 1.1 The Surveyors

The Seller has engaged the Surveyors to provide the Report and a Generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited energy company.

The Surveyors are authorised to provide a transcript or retype of the Generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by brokers and lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the Generic Mortgage Valuation Report and the Report. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the Generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and Generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors are required to amend the valuation in consequence of such information, they will issue an amended Report and Generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and Generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon residential property. \*

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's agent or relative to the Property, they will be obliged to indicate this in the adjacent box.  Yes

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

\* Which shall be in accordance with the current RICS Appraisal and Valuation Standards (The Red Book) and RICS Rules of Conduct.

#### 1.2 The Report

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to the 1st of December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Report is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Report may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective Purchasers and the Purchaser and their respective professional advisors without the prior written consent of the Surveyors.

### 1.3 Liability

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and is prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would be (or, as the case might be, would have been) disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisors of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

Graham + Sibbald's total liability to the Client (and any third party relying upon this report) under this Agreement (including liability in contract, tort (including negligence), breach of statutory duty, or otherwise) shall be limited to the lower of the

### 1.4 Generic Mortgage Valuation Report

The Surveyors undertake to the Seller that they will prepare a Generic Mortgage Valuation Report, which will be issued along with the Report. It is the responsibility of the Seller to ensure that the Generic Mortgage Valuation Report is provided to every potential Purchaser.

### 1.5 Transcript Mortgage Valuation for Lending Purposes

The Surveyors undertake that on being asked to do so by a prospective Purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. \*\* The Transcript Mortgage Valuation Report for Lending Purposes will be prepared from information contained in the Report and the Generic Mortgage Valuation Report.

\*\* Which shall be in accordance with the current RICS Appraisal and Valuation Standards (The Red Book) and RICS Rules of Conduct.

### 1.6 Intellectual Property

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 Payment

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports, including replacement home reports.

#### 1.8 Cancellation

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the Property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the Property, the Surveyor concludes that the Property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the following paragraph of this section.

In the case of cancellation by the Seller, for whatsoever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

If our account details change, we will notify these to you by letter or face to face and never by email.

#### 1.9 Precedence

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.10 Definitions

the Lender is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;

the Transcript Mortgage Valuation Report for Lending Purposes means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a Surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;

the Generic Mortgage Valuation Report means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.

the Market Value is the estimated amount for which the Property should exchange, on the date of valuation, between a willing seller and a willing buyer in an arms length transaction after proper marketing where the parties had each acted knowledgeably, prudently and without compulsion;

the Property is the property which forms the subject of the Report;

the Purchaser is the person (or persons) who enters into a contract to buy the Property from the Seller;

a prospective Purchaser is anyone considering buying the Property;

the Report is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in Part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;

the Seller is/are the proprietor(s) of the Property;

the Surveyor is the author of the Report on the Property;

the Surveyors are Graham + Sibbald LLP, a limited liability partnership incorporated in Scotland (Registered Number SO307130) and having its registered office address at Seabraes House, 18 Greenmarket, Dundee, DD1 4QB, of which the Surveyor is an employee, director or member (unless the Surveyor is not an employee, director or member, when the Surveyors means the Surveyor) whose details are set out at the head of the Report; and



the Energy Report is the advice given by the accredited energy company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

"Data Protection Legislation" means the UK Data Protection Legislation and any other European Union legislation relating to personal data and all other legislation and regulatory requirements in force from time to time which apply to a party relating to the use of personal data (including, without limitation, the privacy of electronic communications).

"UK Data Protection Legislation" means all applicable data protection and privacy legislation in force from time to time in the UK including the UK GDPR; the Data Protection Act 2018; the Privacy and Electronic Communications Directive 2002/58/EC (as updated by Directive 2009/136/EC) and the Privacy and Electronic Communications Regulations 2003 (SI 2003/2426) as amended.

"UK GDPR" has the meaning given to it in section 3(10) (as supplemented by section 205(4)) of the Data Protection Act 2018.

## DESCRIPTION OF THE REPORT

### 2.1 The Service

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by statute and this is in the format of the accredited energy company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

### 2.2 The Inspection

The inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the Property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the Property.

The inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the Report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Report of Property that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a register of asbestos and effective management plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

### 2.3 The Report

The Report will be prepared by the Surveyor who carried out the Property inspection and will describe various aspects of the Property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the Property will be concise and will be restricted to matters that could have a material affect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the Property is free of any other minor defects.

Throughout the Report the following repair categories will be used to give an overall opinion of the state of repair and condition of the Property:

#### 2.3.1 Category 3:

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the Property or cause a safety hazard. Estimates for repairs or replacement are needed now.

### 2.3.2 Category 2:

Repairs or replacement requiring future attention, but estimates are still advised.

### 2.3.3 Category 1:

No immediate action or repair is needed.

#### WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the Property. This is particularly true during slow market conditions when the effect can be considerable. Parts of the Property which cannot be seen or accessed will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

### 2.4 Services

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

### 2.5 Accessibility

A section is included to help identify the basic information interested parties need to know to decide whether to view a Property.

### 2.6 Energy Report

A section is included that makes provision for an Energy Report, relative to the Property. The Surveyor will collect physical data from the Property and provide such data in a format required by an accredited Energy company. The Surveyor cannot of course accept liability for any advice given by the energy company.

### 2.7 Valuation & Conveyancer Issues

The last section of the Report contains matters considered relevant to the conveyancer (solicitor). It also contains the Surveyors opinion both of the market value of the Property and of the re-instatement cost, as defined below.

**Market Value** is the estimated amount for which a property should exchange on the date of valuation within a willing buyer and willing seller in an arms-length transaction after proper marketing wherein the parties have each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of uninspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;

There are no particularly troublesome or unusual legal restrictions.

There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

**Re-instatement cost** is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a re-inspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

It is assumed that any relevant Local Authority consents, warrants and completion certificates have been obtained where construction or alteration works have been undertaken.

This agreement and any dispute or claim arising out of or in connection with its subject matter shall be governed by and construed in accordance with the laws of Scotland, and the Scottish Courts will have exclusive jurisdiction to hear such claims.

#### DATA PROTECTION

Graham + Sibbald and the Client each undertake that:

- (a) they shall comply with all applicable requirements of the Data Protection Legislation, including without limitation any obligations relating to the rights of a data subject and the reporting of personal data breaches (all as defined in the UK GDPR); and
- (b) not do or omit to do anything which puts any other party to the Agreement in breach of the Data Protection Legislation.

Without prejudice to the generality of this clause, you shall ensure that you have all necessary appropriate consents and notices in place to enable lawful transfer of the personal data to Graham + Sibbald for the duration and purposes of this Agreement. You shall have liability for and shall indemnify Graham + Sibbald for any loss, liability, costs (including legal costs), damages, or expenses resulting from any breach by you of the Data Protection Legislation. For further information regarding how Graham + Sibbald processes personal data in relation to this Agreement, please see Graham + Sibbald's privacy notice on their website.

# Mortgage Valuation Report for Home Report



Source: G+S Home Report

Seller Name:

Reference:

## 1) Property Details

House Name:   
Number / Ext:    
Street:   
Area:   
Town:  Postcode:

## 2) Description of property

Property Type:  House Type:  Floor number of subject property:   
Year Built:  Non Traditional Construction?:  No. of floors in block:   
(\*Specify under general comments) No. of flats in block:

## 3) Accommodation - give number of:

Receptions:  Bedrooms:  Kitchens:  Bathrooms:  Total Inside W.C.s:  No of floors:   
Other:  Garage(s):  Outbuildings:  Garden:

## 4) Tenure:

If Leasehold, years unexpired:

Any known or reported problems with onerous or unusual ground rent or service charges?

Owner occupied:  Tenanted:  Vacant:

If part tenanted, please give details

## 5) Subsidence, Settlement and Landslip

Does the property show signs of, or is the property located near any area subject to landslip, heave, settlement, subsidence, flooding or mining?

If yes, please clarify:

## 6) Condition of Property

Are essential internal repairs required? Yes  No   
Are essential external repairs required? Yes  No   
Should the repairs be effected before the advance is made? Yes  No   
Is a mortgage retention recommended? Yes  No

If the answer to any of the above questions is Yes, please provide further detail:



7) Services Mains water  Mains drainage  Electricity  Gas  Central heating


8) Insurance Reinstatement Value  
 Total area of all floors measured internally (m<sup>2</sup>)   
 Cost of rebuilding inc. demolition, site clearance, professional fees, local authority requirements and main building (inc all other structures within the site boundaries unless specifically excluded)

9) Market Valuation for Mortgage Purposes (Assuming Vacant Possession)  
 Comment on mortgageability

Valuation in present condition:   
 Valuation on completion of any works required under Question 6:

10) General Comments  
 Please advise of any special features of the property and/or the location, which affects the property.  
 The subjects comprise a substantial semi-detached two storey B listed villa located within an established residential area to the west of Dundee City. Adequate facilities can be found within easy reach.  
 Externally, we noted no evidence of serious defect to the main fabric although due to the age of the property ongoing maintenance should be anticipated. The roof covering is original and will require regular maintenance. The retaining walls have been patched and repaired in the past although these are under pressure and should be monitored.  
 Internally, fixtures and fittings are on serviceable lines and decoration is to a good standard throughout. While defects were noted, these are commonly found in a property of this type and as far as possible have been reflected within the valuation.  
 A check should be made to ascertain if any timber specialist repair works have been carried out within the property in the past and all reports and guarantees should be obtained, studied and authenticated prior to purchase. Staining was noted to the roof timbers and slight dampness was noted within the utility room. It is recommended that a timber specialist firm is instructed prior to purchase to carry out a full inspection of the property as a precautionary measure.  
 Alterations have been carried out within the property and it is assumed that any necessary consents were obtained.

IMPORTANT - THIS IS A CONFIDENTIAL REPORT PREPARED FOR MORTGAGE PURPOSES  
 Certificate: I have personally inspected the property described herein and confirm adequate professional indemnity cover is held.

Signature   
 Valuer name and qualification Graham Tonner MRICS  
 For and on behalf of Graham + Sibbald LLP  
 Date of inspection   
 Date of report

Company / Firm Name Graham + Sibbald LLP  
 Office Name   
 Office Addr1   
 Office Addr2   
 Area   
 Town   
 Postcode   
 Tel no



In these Terms and Conditions of Engagement, the following expressions shall have the following meanings:

"Agreement" means these Terms and Conditions of Engagement, the Instructions and the confirmation letter issued by Graham + Sibbald.

"Client" / "you" / "your" means the person, firm, company, organisation or other entity engaging Graham + Sibbald to provide the inspection services.

"Data Protection Legislation" means the UK Data Protection Legislation and any other European Union legislation relating to personal data and all other legislation and regulatory requirements in force from time to time which apply to a party relating to the use of personal data (including without limitation, the privacy of electronic communications).

"Graham + Sibbald" / "we" / "us" / "our" means Graham + Sibbald LLP, a limited liability partnership incorporated in Scotland (Registered Number SO307130) and having its registered office address at Seabraes House, 18 Greenmarket, Dundee, DD1 4QB.

"Instructions" means the written or verbal instructions by the Client to Graham + Sibbald, which appoint Graham + Sibbald to provide the inspection services.

"Property" means the property identified and described in the Instructions.

"UK Data Protection Legislation" means all applicable data protection and privacy legislation in force from time to time in the UK including the UK GDPR, the Data Protection Act 2018, the Privacy and Electronic Communications Directive 2002/58/EC (as updated by Directive 2009/136/EC) and the Privacy and Electronic Communications Regulations 2003 (SI 2003/2426) as amended.

"UK GDPR" has the meaning given to it in section 3(10) (as supplemented by section 205(4)) of the Data Protection Act 2018.

A valuation for mortgage is a limited inspection and report produced for buildings societies, banks and other lenders to enable them to make a lending decision. IT IS NOT A SURVEY. Unless otherwise stated the date of valuation will be the date of inspection.

This report is used to guide the lender on the market value of the Property for mortgage purposes and is carried out for this purpose alone. Although the inspection will be carried out by a valuer who will usually be a qualified surveyor it is not a detailed inspection of the Property, and only major visible defects will be noted. Subject to reasonable accessibility, the roof space is inspected only to the extent visible from the access hatch without entering it. The surveyor will not inspect under floor areas, communal roof space or other parts not readily accessible. The exterior and roof of the Property will be inspected from ground level only from within the boundaries of the site and adjacent communal public areas. The area of the Property will be taken into account, and the rooms individually inspected, but floor coverings and furniture will not be moved. Services (such as water, gas, electricity and drainage) will not be tested and we will not advise as to whether these comply with regulations in respect of these services.

The surveyor may recommend that a part of the mortgage be retained by the lenders until such time as particular repair works are carried out. Similarly, the report may suggest that the borrower should undertake to carry out certain repairs or commission more extensive investigation where hidden defects are suspected since these may have a material effect on the value of the Property. If a retention is recommended then the figure should not be regarded as an estimate of repair costs. Its purpose is to protect the interests of the lending institution. It is recommended that detailed estimates be obtained before proceeding with the purchase. Attention is drawn to the fact that if a subsequent transcription of this report is prepared on a lenders form, then in order to comply with the lenders specific requirements, the wording or phrasing may differ. Many people rely on the mortgage valuation certificate in the mistaken belief that it is a detailed survey. The report is often made available to house buyers by lenders, but this does not mean that it should be relied upon as a report on the condition of the building.

The definition of 'market value' is the estimated amount for which a Property should exchange on the date of valuation, between a willing buyer and a willing seller in an arms-length transaction after proper marketing wherein the parties had acted knowledgeably, prudently and without compulsion. For the purpose of this market value the surveyor has assumed that vacant possession will be provided. Unless otherwise stated the surveyor has valued the interest on a comparable basis.

The inspection that has been undertaken should not be regarded as a survey. The surveyor did not inspect parts of the Property which were covered, unexposed or inaccessible and are therefore unable to report that any such part of the Property is free from defect. Defects which are not considered materially to affect the value of the Property or other matters which would be attended to during maintenance, may not have been mentioned. If defects have been mentioned in this report, they should be regarded as indicative and not exhaustive. For the purposes of this valuation the surveyor assumes that all uninspected areas are free from defect which would have a material effect on value.

In accordance with our normal practice, we must state that this report is for the use only of the party to whom it is addressed or their named client and no responsibility is accepted to any third party for the whole or any part of its content.

In addition, we would bring to your attention that neither the whole nor any part of this report, nor any reference thereto, may be included in any document, circular or statement without prior written approval of the form and context in which it will appear.

The surveyor shall, unless otherwise expressly agreed, rely upon information provided by the Client and/or the Client's legal or other professional advisers relating to tenure, leases and all other relevant matters.

For the purposes of this valuation the surveyor has assumed that all ground burdens are nominal or have been redeemed and that there are no unusual outgoings or onerous restrictions contained within the titles of which we have no knowledge. The surveyor has further assumed that the subjects are unaffected by any adverse planning proposals.

Unless otherwise stated, it is assumed that all the required valid planning permissions and statutory approvals for the building and for their use, including any recent or significant extensions or alterations, have been obtained and complied with. It has been further assumed that no deleterious or hazardous materials or techniques have been used in the construction of the subject and that there is no contamination in or from the ground or from the immediate surrounds.

The surveyor will not carry out an asbestos inspection and will not be acting as an asbestos inspector in completing a valuation inspection of Property that may fall within the Control of Asbestos Regulations 2012. No enquiry of the duty holder, as defined in the Control of Asbestos Regulations 2012, of the existence of an asbestos register, or of any plan for the management of asbestos will be made. Your legal adviser/conveyancer should confirm the duty holder under these regulations, the availability of an asbestos register and the existence and management of any asbestos containing materials. For the purposes of this valuation, the surveyor has assumed that there is a duty holder, as defined in the Control of Asbestos Regulations 2012, and that a register of asbestos and effective management plan is in place which does not require any immediate expenditure or pose a significant risk to health or breach the HSE Regulations.

The surveyor confirms that this mortgage valuation is prepared in accordance with the RICS Valuation - Global Standards 2017 and incorporating IVSC International Valuation Standards and, unless otherwise stated, we are External Valuers as defined therein. Further information may also be obtained from the Royal Institution of Chartered Surveyors in Scotland, 10 Charlotte Square, Edinburgh EH2 4DR.

As part of this remit, the surveyor may, where he/she feels qualified and experienced to do so, provide general comment on standard appropriate supplementary documentation, presented to us by the Client's lender and conveyancer. In the event of a significant amount of documentation being provided to us, an additional fee may be incurred. Any additional fees will be agreed with you in advance.

We confirm that Graham + Sibbald operates formal procedures to deal with complaints from clients in accordance with By-Law 19, Regulation 2.7 of the Royal Institution of Chartered Surveyors Rules of Conduct and Disciplinary Procedures. A copy of this procedure is available on request.

Graham + Sibbald's total liability to the Client (and any third party relying upon this report) under this Agreement (including liability in contract, tort (including negligence), breach of statutory duty, or otherwise) shall be limited to the lower of the following a) 25% of the valuation or b) £250,000.

This agreement and any dispute or claim arising out of or in connection with its subject matter shall be governed by and construed in accordance with the laws of Scotland, and the Scottish courts will have exclusive jurisdiction to hear such claims.

Graham + Sibbald and the Client each undertake that: (a) they shall comply with all applicable requirements of the Data Protection Legislation, including without limitation any obligations relating to the rights of a data subject and the reporting of personal data breaches (all as defined in the UK GDPR); and (b) not do or omit to do anything which puts any other party to the Agreement in breach of the Data Protection Legislation.

Without prejudice to the generality of this clause, you shall ensure that you have all necessary appropriate consents and notices in place to enable lawful transfer of the personal data to Graham + Sibbald for the duration and purposes of this Agreement. You shall have liability for and shall indemnify Graham + Sibbald for any loss, liability, costs (including legal costs), damages, or expenses resulting from any breach by you of the Data Protection Legislation. For further information regarding how Graham + Sibbald processes personal data in relation to this Agreement, please see Graham + Sibbald's privacy notice available via our website.

# Energy Performance Certificate (EPC)

# Scotland

Dwellings

269 PERTH ROAD, DUNDEE, DD2 1JP

**Dwelling type:** Semi-detached house  
**Date of assessment:** 03 December 2024  
**Date of certificate:** 04 December 2024  
**Total floor area:** 267 m<sup>2</sup>  
**Primary Energy Indicator:** 270 kWh/m<sup>2</sup>/year


**Reference number:** 9190-2427-0220-2904-2585  
**Type of assessment:** RdSAP, existing dwelling  
**Approved Organisation:** Elmhurst  
**Main heating and fuel:** Boiler and radiators, mains gas

## You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

|  |                |  |
|--|----------------|--|
| <b>Estimated energy costs for your home for 3 years*</b> | <b>£11,163</b> | See your recommendations report for more information |
| <b>Over 3 years you could save*</b>                      | <b>£4,011</b>  |  |

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




## Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (63)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



## Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band E (53)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Top actions you can take to save money and make your home more efficient

| Recommended measures                   | Indicative cost  | Typical savings over 3 years |
|--|------------------|------------------------------|
| 1 Internal or external wall insulation | £4,000 - £14,000 | £2634.00                     |
| 2 Floor insulation (suspended floor)   | £800 - £1,200    | £618.00                      |
| 3 Solar water heating                  | £4,000 - £6,000  | £270.00                      |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit [greenerscotland.org](http://greenerscotland.org) or contact Home Energy Scotland on 0808 808 2282.

**THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

## Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element               | Description  | Energy Efficiency | Environmental |
|-----------------------|--|-------------------|---------------|
| Walls                 | Sandstone or limestone, as built, no insulation (assumed)            | ★★☆☆☆             | ★★☆☆☆         |
| Roof                  | Pitched, 300 mm loft insulation                                      | ★★★★★             | ★★★★★         |
| Floor                 | Suspended, no insulation (assumed)<br>Solid, no insulation (assumed) | —<br>—            | —<br>—        |
| Windows               | Partial double glazing   | ★★☆☆☆             | ★★☆☆☆         |
| Main heating          | Boiler and radiators, mains gas                                      | ★★★★☆             | ★★★★☆         |
| Main heating controls | Programmer, room thermostat and TRVs                                 | ★★★★☆             | ★★★★☆         |
| Secondary heating     | None   | —                 | —             |
| Hot water             | From main system   | ★★★★☆             | ★★★★☆         |
| Lighting              | Low energy lighting in all fixed outlets                             | ★★★★★             | ★★★★★         |

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

## The impact of your home on the environment


One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 48 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 13 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 6.0 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.













### Estimated energy costs for this home

|               | Current energy costs | Potential energy costs | Potential future savings  |
|---------------|----------------------|------------------------|---|
| Heating       | £9,903 over 3 years  | £6,219 over 3 years    |  |
| Hot water     | £726 over 3 years    | £393 over 3 years      |   |
| Lighting      | £534 over 3 years    | £540 over 3 years      |   |
| <b>Totals</b> | <b>£11,163</b>       | <b>£7,152</b>          |   |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

### Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

| Recommended measures   | Indicative cost  | Typical saving per year | Rating after improvement  |   |
|--|------------------|-------------------------|---|---|
|  |                  |                         | Energy  | Environment   |
| 1 Internal or external wall insulation                           | £4,000 - £14,000 | £878                    |  |  |
| 2 Floor insulation (suspended floor)                             | £800 - £1,200    | £206                    |  |  |
| 3 Solar water heating  | £4,000 - £6,000  | £90                     |  |  |
| 4 Replace single glazed windows with low-E double glazed windows | £3,300 - £6,500  | £163                    |  |  |
| 5 Solar photovoltaic panels, 2.5 kWp                             | £3,500 - £5,500  | £414                    |  |  |

### Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to [www.greenerscotland.org](http://www.greenerscotland.org).



## About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

### 1 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide long-lasting weather protection. Further information can be obtained from the National Insulation Association ([www.nationalinsulationassociation.org.uk](http://www.nationalinsulationassociation.org.uk)). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

### 2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including [www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation](http://www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation). Building regulations generally apply to this work so it is best to check with your local authority building standards department.

### 3 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

### 4 Double glazed windows

Double glazing is the term given to a system where two panes of glass are made up into a sealed unit. Replacing existing single-glazed windows with double-glazed windows will improve comfort in the home by reducing draughts and cold spots near windows. Double-glazed windows may also reduce noise, improve security and combat problems with condensation. Building regulations apply to this work and planning permission may also be required, so it is best to check with your local authority on what standards need to be met. A building warrant is not required if the windows comply with the current requirements.

### 5 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at [www.microgenerationcertification.org](http://www.microgenerationcertification.org).

## Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

**LZC energy sources present:** There are none provided for this home

## Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

| Heat demand                  | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 47,588            | N/A                       | N/A                              | (13,286)                        |
| Water heating (kWh per year) | 3,510             |                           |                                  |                                 |

## Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

## About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst ([www.elmhurstenergy.co.uk](http://www.elmhurstenergy.co.uk)), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk) and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Graham Tonner  
Assessor membership number: EES/009482  
Company name/trading name: Graham & Sibbald  
Address: Seabraes House 18 Greenmarket  
Dundee  
DD1 4QB  
Phone number: 01382 200064  
Email address: [dundee@g-s.co.uk](mailto:dundee@g-s.co.uk)  
Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

## Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk), with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at [www.gov.scot/epc](http://www.gov.scot/epc).

## **Advice and support to improve this property**

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

**HOMEENERGYSCOTLAND.ORG**  
**0808 808 2282**  
FUNDED BY THE SCOTTISH GOVERNMENT



# property questionnaire

|                  |                                     |
|------------------|-------------------------------------|
| Property address | 269 Perth Road<br>Dundee<br>DD2 1JP |
|------------------|-------------------------------------|

|           |                     |
|-----------|---------------------|
| Seller(s) | Catherine Jean Muir |
|-----------|---------------------|

|   |            |
|---|------------|
| Completion date of property questionnaire | 04/12/2024 |
|---|------------|

## Note for sellers

- x Please complete this form carefully. It is important that your answers are correct.
- x The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- x If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

## Information to be given to prospective buyer(s)

|    |   |     |
|----|---|-----|
| 1. | Length of ownership   |     |
|    | How long have you owned the property? 12 years  |     |
| 2. | Council tax   |     |
|    | Which Council Tax band is your property in? F   |     |
| 3. | Parking   |     |
|    | <p>What are the arrangements for parking at your property?<br/>(Please tick all that apply)</p> <p><input checked="" type="checkbox"/> Garage <span style="float: right;">Yes</span></p> <p><input checked="" type="checkbox"/> Allocated parking space</p> <p><input checked="" type="checkbox"/> Driveway <span style="float: right;">Yes</span></p> <p><input checked="" type="checkbox"/> Shared parking</p> <p><input checked="" type="checkbox"/> On street <span style="float: right;">Yes</span></p> <p><input checked="" type="checkbox"/> Resident permit</p> <p><input checked="" type="checkbox"/> Metered parking</p> <p><input checked="" type="checkbox"/> Other (please specify):</p> |     |
| 4. | Conservation area   |     |
|    | Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?  | Yes |

|    |   |     |
|----|---|-----|
| 5. | Listed buildings  |     |
|    | Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?  | Yes |
| 6. | Alterations/additions/extensions  |     |
| a. | <p>(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?</p> <p>If you have answered yes, please describe below the changes which you have made:</p>  | No  |
|    | <p>(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?</p> <p>If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.</p> <p>If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:</p> |     |
| b. | <p>Have you had replacement windows, doors, patio doors or double glazing installed in your property?</p> <p>If you have answered yes, please answer the three questions below:</p>   | No  |
|    | (i) Were the replacements the same shape and type as the ones you replaced?   |     |
|    | (ii) Did this work involve any changes to the window or door openings?  |     |
|    | <p>(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):</p> <p>Please give any guarantees which you received for this work to your solicitor or estate agent.</p>  |     |

|    |  |              |
|----|--|--------------|
| 7. | Central heating  |              |
| a. | <p>Is there a central heating system in your property?<br/>         (Note: a partial central heating system is one which does not heat all the main rooms of the property <sup>2</sup> the main living room, the bedroom(s), the hall and the bathroom).</p> <p>If you have answered yes or partial _____ ± what kind of central heating is there?<br/>         (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).<br/>         Mains gas central heating</p> <p>If you have answered yes ____, please answer the three questions below:</p> | Yes          |
|    | (i) When was your central heating system or partial central heating system installed?<br>31/10/2023  |              |
|    | (ii) Do you have a maintenance contract for the central heating system?<br>If you have answered yes, please give details of the company with which you have a maintenance contract:  | No           |
|    | (iii) When was your maintenance agreement last renewed?<br>(Please provide the month and year).  |              |
| 8. | Energy Performance Certificate   |              |
|    | Does your property have an Energy Performance Certificate which is less than 10 years old?   | Yes          |
| 9. | Issues that may have affected your property  |              |
| a. | <p>Has there been any storm, flood, fire or other structural damage to your property while you have owned it?</p> <p>If you have answered yes ____, is the damage the subject of any outstanding insurance claim?</p>  | No<br><br>No |
| b. | <p>Are you aware of the existence of asbestos in your property?</p> <p>If you have answered yes ____, please give details:</p>   | No           |



|     |          |  |
|-----|----------|--|
| 10. | Services |  |
|-----|----------|--|

a. Please tick which services are connected to your property and give details of the supplier:

| Services                            | Connected | Supplier            |
|-------------------------------------|-----------|---------------------|
| Gas or liquid petroleum gas         | Yes       | EON                 |
| Water mains or private water supply | Yes       | Dundee City Council |
| Electricity                         | Yes       | EON                 |
| Mains drainage                      | Yes       | Dundee City Council |
| Telephone                           | Yes       | Virgin              |
| Cable TV or satellite               | Yes       | Virgin              |
| Broadband                           | Yes       | Virgin              |

|    |  |    |
|----|--|----|
| b. | Is there a septic tank system at your property?<br><u>If you have answered yes</u> ____, please answer the two questions below:  | No |
|    | (iv) Do you have appropriate consents for the discharge from your septic tank?   |    |
|    | (v) Do you have a maintenance contract for your septic tank?<br><u>If you have answered yes</u> ____, please give details of the company with which you have a maintenance contract: |    |

|     |   |    |
|-----|---|----|
| 11. | Responsibilities for shared or common areas   |    |
| a.  | Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?<br><br><u>If you have answered yes</u> ____, please give details:   | No |
| b.  | Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?<br><br><u>If you have answered yes</u> ____, please give details:  | No |
| c.  | Has there been any major repair or replacement of any part of the roof during the time you have owned the property?   | No |
| d.  | Do you have the right to walk over any of your neighbours' property <sup>2</sup> for example to put out your rubbish bin or to maintain your boundaries?<br><br><u>If you have answered yes</u> ____, please give details:  | No |
| e.  | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?<br><br><u>If you have answered yes</u> ____, please give details:   | No |
| f.  | As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)<br><br><u>If you have answered yes</u> ____, please give details: | No |
| 12. | Charges associated with your property   |    |
| a.  | Is there a factor or property manager for your property?<br><br><u>If you have answered yes</u> ____, please provide the name and address, and give details of any deposit held and approximate charges:  | No |

|     |   |    |
|-----|---|----|
| b.  | <p>Is there a common buildings insurance policy?</p> <p>If you have answered yes, is the cost of the insurance included in your monthly/annual factor charges?</p>  | No |
| c.  | <p>Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents association, or maintenance or stair fund.</p>  |    |
| 13. | Specialist works  |    |
| a.  | <p>As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?</p> <p><u>If you have answered yes</u> , please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.</p>   | No |
| b.  | <p>As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?</p> <p><u>If you have answered yes</u> , please give details:</p>   | No |
| c.  | <p><u>If you have answered yes</u> to 13(a) or (b), do you have any guarantees relating to this work?</p> <p><u>If you have answered yes</u> , these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please write below who has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.</p> <p>Guarantees are held by:</p> |    |

|       |   |            |
|-------|---|------------|
| 14.   | Guarantees  |            |
| a.    | Are there any guarantees or warranties for any of the following:  |            |
|       |   |            |
| (i)   | Electrical work   | Don't Know |
| (ii)  | Roofing   | Don't Know |
| (iii) | Central heating   | Don't Know |
| (iv)  | National House Building Council (NHBC)  | Don't Know |
| (v)   | Damp course   | Don't Know |
| (vi)  | Any other work or installations?<br>(for example, cavity wall insulation,<br>underpinning, indemnity policy)                                      | Don't Know |
| b.    | If you have answered <u>yes</u> or <u>with title deeds</u> please give details of the work or installations to which the guarantee(s) relate(s):  |            |
| c.    | Are there any outstanding claims under any of the guarantees listed above?<br><br>If you have answered <u>yes</u> , please give details:          | No         |
| 15.   | Boundaries  |            |
|       | So far as you are aware, has any boundary of your property been moved in the last 10 years?<br><br>If you have answered yes, please give details: | No         |

|   |   |    |
|---|---|----|
| 16.   | Notices that affect your property   |    |
| In the past three years have you ever received a notice:  |   |    |
| a.  | advising that the owner of a neighbouring property has made a planning application? | No |
| b.  | that affects your property in some other way?                                       | No |
| c.  | that requires you to do any maintenance, repairs or improvements to your property?  | No |
| If you have answered yes to any of a <del>to</del> above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property. |   |    |

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

I ACCEPT ;

Name : Catherine Muir

Date: 04/12/2024